

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
Shinichi HARA et al.	;	Examiner: D. Ben Esplin
Application No.: 09/818,625)	Group Art Unit: 2851
Filed: March 28, 2001)	
For: EXPOSURE APPARATUS, GAS REPLACEMENT METHOD, SEMICONDUCTOR DEVICE MANUFACTURING METHOD, SEMICONDUCTOR MANUFACTURING FACTORY AND EXPOSURE APPARATUS MAINTENANCE METHOD	·) :) :) :)	July 7, 2004 Certificate JUL 1 2 2004
U.S. Patent No. 6,714,277 B2)	JUL 1 2 2004 Of Correction
Issued: March 30, 2004)	

The Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and

Trademark Office due to errors which appear in the printed patent as a result of Patent and

Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent

and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

07/09/2004 FMEKONEI 00000010 6714277

- 1 -

Or FC:1811

4

100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentees' undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

DC_MAIN 170738v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,714,277 B2

DATED March 30, 2004

INVENTOR(S): Shinichi HARA et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 53, "On" should read -- At --. Line 55, "On" should read -- At --.

COLUMN 2:

Line 13, "a vessel which airtightly" should read -- an airtight vessel which --.

COLUMN 18:

Lines 25-30 should be deleted. Line 62, "influence" should read -- influences --.

MAILING ADDRESS OF SENDER:

FORM PTO 1050 (REV. 3.82)

PATENT NO. <u>6,714,277 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page



PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,714,277 B2

DATED March 30, 2004

Shinichi HARA et al. INVENTOR(S):

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 37, "vender" should read -- vendor --. Line 40, "vender," should read -- vendor, --.

COLUMN 24:

Line 25, "camber" should read -- chamber --.

Line 46, "whererin" should read -- wherein --.

Line 67, "displacement," should read -- displacement, and --.

COLUMN 25:

Line 16, "via movable" should read -- via a movable --.

Line 21, "said" should read -- wherein said --.

Line 25, "wherein" should read -- wherein the --.

MAILING ADDRESS OF SENDER:

FORM PTO 1050 (REV. 3.82)

PATENT NO. <u>6,714,277 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Staple Here Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,714,277 B2

DATED March 30, 2004

INVENTOR(S): Shinichi HARA et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 26:

Line 12, "manufactoring" should read -- manufacturing --.

Line 37, manufactoring" should read -- manufacturing --.

Line 41, the second occurrence of "in order" should be deleted.


MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,714,277 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

FORM PTO 1050 (REV. 3.82)



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
Shinichi HARA et al.	Examiner: D. Ben Esplin
Application No.: 09/818,625	Group Art Unit: 2851
Filed: March 28, 2001	·)
For: EXPOSURE APPARATUS, GAS REPLACEMENT METHOD, SEMICONDUCTOR DEVICE MANUFACTURING METHOD, SEMICONDUCTOR MANUFACTURING FACTORY AND EXPOSURE APPARATUS MAINTENANCE METHOD	July 7, 2004...
U.S. Patent No. 6,714,277 B2	·)
Issued: March 30, 2004	;)

The Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and
Trademark Office due to errors which appear in the printed patent as a result of Patent and
Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent
and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentees' undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

DC_MAIN 170738v1

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,714,277 B2

March 30, 2004 **DATED**

Shinichi HARA et al. INVENTOR(S):

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 53, "On" should read -- At --. Line 55, "On" should read -- At --.

COLUMN 2:

Line 13, "a vessel which airtightly" should read -- an airtight vessel which --.

COLUMN 18:

Lines 25-30 should be deleted.

Line 62, "influence" should read -- influences --.


MAILING ADDRESS OF SENDER:

FORM PTO 1050 (REV. 3.82)

PATENT NO. <u>6,714,277 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,714,277 B2

DATED : March 30, 2004

INVENTOR(S): Shinichi HARA et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 37, "vender" should read -- vendor --.

Line 40, "vender," should read -- vendor, --.

COLUMN 24:

Line 25, "camber" should read -- chamber --.

Line 46, "whererin" should read -- wherein --.

Line 67, "displacement," should read -- displacement, and --.

COLUMN 25:

Line 16, "via movable" should read -- via a movable --.

Line 21, "said" should read -- wherein said --.

Line 25, "wherein" should read -- wherein the --.

MAILING ADDRESS OF SENDER:

FORM PTO 1050 (REV. 3.82)

PATENT NO. <u>6,714,277 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,714,277 B2

DATED : March 30, 2004

INVENTOR(S): Shinichi HARA et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 26:

Line 12, "manufactoring" should read -- manufacturing --.

Line 37, manufactoring" should read -- manufacturing --.

Line 41, the second occurrence of "in order" should be deleted.

MAILING ADDRESS OF SENDER:

FORM PTO 1050 (REV. 3.82)

PATENT NO. <u>6,714,277 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page



DC_MAIN 170737v1